		C		
DeKa	alb	Co	un	ty

Development Services Center 178 Sams Street Decatur, GA 30030 www.dekalbcountyga.gov/planning 404-371-2155 (o); 404-371-4556 (f)

Chief Executive Officer D Michael Thurmond	EPARTMENT OF F	PLAN	NING & SUST	AINABI	LITY Interim Director Cedric Hudson
	Application for	Certifi	cate of Appro	priatenes	S
Date submitted:		Date Re	ceived:		
Address of Subject Propert	y: 1035 Oxford Rd				
Applicant: Ben Darn	ner / Parkwood Liv	ing, L	LC E-Mai	bdarmer@bellso	uth.net / info@parkwoodliving.com
Applicant Mailing Address	1877 Ardmore R	d Atla	anta, GA 3030)9 /	
951 Edgewood /	Ave Atlanta, GA 30	307			
Applicant Phone: 404-6	95-0690 / 404-438	8-612	0		
Applicant's relationship to	the owner: Owner	Arch	itect Cont	ractor/Builde	r Other
***************************** Christopher Owner(s): Gerard Whit	י J White, Trustee Ke\ e Trust	******** /in	cjwhited	ds@gmail.c	**************************************
Owner(s):			Email:		
Owner(s) Mailing Address	1035 Oxford Road, A	tlanta	GA 30306		
Owner(s) Telephone Numl	per:				
Approximate date of const	ruction of the primary structu	re on the	e property and any ot	her structures	s affected by this project:
Nature of work (check all t	hat apply): New construction	~	New Accessory Build	ling	Other Building Changes
	Demolition	~	Landscaping	~	Other Environmental Changes
	Addition		Fence/Wall	~	Other
Description of Work:	Moving a Building		Sign Installation		
Demolish existing sibasemnt that includ exact location as the remai in the same lo	ingle family home. Bu es a two car drive und e existing structure, in ocation.	ild a n der ga icludin	ew single famil rage. The new g a similar widt	y residnec home will h. The cui	e that is two stories with be placed in an almost th rbcut/driveway apron will

This form must be completed in its entirety and be accompanied by supporting documents, such as plans, list of materials, color samples, photographs, etc. All documents should be in PDF format, except for photographs, which may be in JPEG format. Email the application and supporting material to <u>plansustain@dekalbcountyga.gov</u> and <u>pvjennings@dekalbcountyga.gov</u>. An incomplete application will not be accepted.

Signature of Applicant:

DEPARTMENT OF PLANNING & SUSTAINABILITY

Authorization of a Second Party to Apply for a Certificate of Appropriateness

This form is required if the individual making the request is **<u>not</u>** the owner of the property.

I/ We:
being owner(s) of the property at: 1035 Oxford Rd.
hereby delegate authority to: Ben Darmer / Parkwood Living, LLC

to file an application for a certificate of appropriateness in my/our behalf.

	Signed by:
Signat	ure of Owner(s)
U	4946298F932C432
Date:	10/3/2024 13:52 PDT

Please review the following information

Approval of this Certificate of Appropriateness does not release the recipient from compliance with all other pertinent county, state, and federal regulations.

Before making any changes to your approved plans, contact the preservation planner (404/371- 2155). Some changes may fall within the scope of the existing approval, but others will require review by the preservation commission. If work is performed which is not in accordance with your certificate, a Stop Work Order may be issued.

If your project requires that the county issue a Certificate of Occupancy at the end of construction, an inspection may be made to verify that the work has been completed in accord with the Certificate of Appropriateness. If the work as completed is not the same as that approved in the Certificate of Appropriateness you will not receive a Certificate of Occupancy. You may also be subject to other penalties including fines and/or required demolition of the non-conforming work.

If you do not commence construction within twelve months of the date of approval, your Certificate of Appropriateness will become void and you will need to apply for a new certificate if you still intend to do the work.

DeKalb County				De 17	evelopment Services Center 78 Sams Street
DeKalb County				De	ecatur, GA 30030 ww.dekalbcountyga.gov/planning
				40)4-371-2155 (o); 404-371-4556 (f
Chief Executive Officer DEPAR	FMENT OF	PLAN	NING & SUSTA	INABILI	ГҮ Interim Director
Michael Thurmond					Cedric Hudson
Ap	plication for	Certif	icate of Appropr	iateness	
Data submitted 10/27/24		Data Da	anian d		
1035	– S Oxford Rd	Date Re	ceived:		
Address of Subject Property:	arkwood Liv	/ing I		darmer@bellsouth n	et / info@parkwoodliving.com
Applicant: Dell Dannel / F		nny, L	E-Mail:	uarmer@beilsouur.n	et / mo@parkwoodilving.com
Applicant Mailing Address: 1877	Ardmore R	d Atla	anta, GA 30309	1	
951 Edgewood Ave At	anta, GA 30)307			
404 605 06	00 / 101 120	0 610	0		
Applicant Phone:	90 / 404-430	5-012			
Applicant's relationship to the owner	: Owner	Arch	nitect Contrac	tor/Builder	Other
**************************************	******************************* e, Trustee Ke	********* vin	**************************************	************** @gmail.com	**************************************
Owner(s): Gerard while Trust			_ Email:		
Owner(s):			Email:		
1035 C Owner(s) Mailing Address:	xford Road, A	tlanta	GA 30306		
Owner(s) Telephone Number:	R				-
Approximate date of construction of t	he primary structu	ire on the	e property and any other	structures aff	ected by this project:
		V	N D 111		_
Nature of work (check all that apply):	New construction		New Accessory Building		Other Building Changes
Nature of work (check all that apply):	New construction Demolition	~	Landscaping	~	Other Building Changes Other Environmental Changes
Nature of work (check all that apply):	New construction Demolition Addition		New Accessory Building Landscaping Fence/Wall	✓	Other Building Changes

Signature of Applicant: ______

Docusign Envelope ID: 0BBCC81E-3EB7-452C-9DAE-70ADB9505796
DeKalb County
DEPARTMENT OF PLANNING & SUSTAINABILITY
Authorization of a Second Party to Apply for a Certificate of Appropriateness
This form is required if the individual making the request is not the owner of the property.
I/We: CHRISTOPHER J. WHITE, TRUSTEE KEVIN GERARD WHITE TRUST
being owner(s) of the property at: 1035 Oxford Rd.
hereby delegate authority to: Ben Darmer / Parkwood Living, LLC
to file an application for a certificate of appropriateness in my/our behalf.
Signed by:
Signature of Owner(s)
Date: PDT
Please review the following information

Approval of this Certificate of Appropriateness does not release the recipient from compliance with all other pertinent county, state, and federal regulations.

Before making any changes to your approved plans, contact the preservation planner (404/371- 2155). Some changes may fall within the scope of the existing approval, but others will require review by the preservation commission. If work is performed which is not in accordance with your certificate, a Stop Work Order may be issued.

If your project requires that the county issue a Certificate of Occupancy at the end of construction, an inspection may be made to verify that the work has been completed in accord with the Certificate of Appropriateness. If the work as completed is not the same as that approved in the Certificate of Appropriateness you will not receive a Certificate of Occupancy. You may also be subject to other penalties including fines and/or required demolition of the non-conforming work.

If you do not commence construction within twelve months of the date of approval, your Certificate of Appropriateness will become void and you will need to apply for a new certificate if you still intend to do the work.

To: Dekalb County Druid Hills Civic Association & The Historic Preservation Commission

Re: 1035 Oxford Road NE Atlanta, GA 30306

I, <u>MCHARE HARREN</u>, the owner located at <u>1022 OAKE PSA0</u> am a neighbor to 1035 Oxford Road NE Atlanta, GA 30306. I believe that the existing home does not have significant historic value, nor does it currently contribute to the Druid Hills Historic District. We give our full support that the current home should be torn down and built back to Druid Hills Historic District standards.

OCTOBER (1, 2024 Name

To: Dekalb County Druid Hills Civic Association &

The Historic Preservation Commission

Re: 1035 Oxford Road NE Atlanta, GA 30306

I, <u>Jodi Bell Woodard</u>, the owner located at <u>IO28 Oxford Rd.</u> am a neighbor to 1035 Oxford Road NE Atlanta, GA 30306. I believe that the existing home does not have significant historic value, nor does it currently contribute to the Druid Hills Historic District. We give our full support that the current home should be torn down and built back to Druid Hills Historic District standards.

Name

Date:

To: Dekalb County Druid Hills Civic Association & The Historic Preservation Commission

Re: 1035 Oxford Road NE Atlanta, GA 30306

I, MARK A. LAMAS , the owner located at 1019 OXFORD RD. N.F. am a neighbor to 1035 Oxford Road NE Atlanta, GA 30306. I believe that the existing home does not have significant historic value, nor does it currently contribute to the Druid Hills Historic District. We give our full support that the current home should be torn down and built back to Druid Hills Historic District standards.

Markh. Jamas 9/14/24

To: Dekalb County Druid Hills Civic Association & The Historic Preservation Commission

Re: 1035 Oxford Road NE Atlanta, GA 30306

I, <u>Jamel Hamrich</u>, the owner located at <u>INDEXTORE ALLE</u> am a neighbor to 1035 Oxford Road NE Atlanta, GA 30306. I believe that the existing home does not have significant historic value, nor does it currently contribute to the Druid Hills Historic District. We give our full support that the current home should be torn down and built back to Druid Hills Historic District standards.

Name:

Date:

To: Dekalb County Druid Hills Civic Association & The Historic Preservation Commission

Re: 1035 Oxford Road NE Atlanta, GA 30306

I, <u>beorge</u> <u>Shepherd</u>, the owner located at <u>1027</u> <u>Oxford</u> <u>Road</u> am a neighbor to 1035 Oxford Road NE Atlanta, GA 30306. I believe that the existing home does not have significant historic value, nor does it currently contribute to the Druid Hills Historic District. We give our full support that the current home should be torn down and built back to Druid Hills Historic District standards.

9/16 2024

To: Dekalb County Druid Hills Civic Association &

The Historic Preservation Commission

Re: 1035 Oxford Road NE Atlanta, GA 30306

I, <u>CRAWN A MONE</u>, the owner located at <u>IOYLE OXFORD</u> <u>MD</u>, am a neighbor to 1035 Oxford Road NE Atlanta, GA 30306. I believe that the existing home does not have significant historic value, nor does it currently contribute to the Druid Hills Historic District. We give our full support that the current home should be torn down and built back to Druid Hills Historic District standards.

Inna Books 9/15/24 Name:



STRUCTURAL ENGINEER INSPECTION REPORT



Site Address: Inspection Date: Prepared by: Phone: Email: 1035 Oxford Rd NE, Atlanta, GA 30306 Friday, August 29, 2024, Harry Wahba, P.E. (Lic. PE039356) (470) 295-3779 fivestarengineeringllc@gmail.com



Do not use this report, form any conclusions or make any commitments unless you have carefully read the entire report. This report describes the condition of the accessible and observable areas of the premises at the time of the inspection. The condition can change substantially after the inspection in ways that cannot be predicted.



Table of Contents

Property Description	3
Scope	3
Observations, Conclusions & Recommendations	3
Special Notice	3
Exhibits	4



Property Description

The property inspected is a single-family house built in 1920 with a basement/crawlspace foundation.

Scope

On August 29, 2024, a site visit was carried out at 1035 Oxford Rd NE, Atlanta, GA, 30306, to inspect and assess the condition, structural stability, and integrity of the building's foundation. The purpose was to determine if the existing foundation was strong enough to support the current structure or needed improvements to accommodate any additions. Our client was concerned about the foundation and wanted to identify any underlying structural issues.

During the external visual inspection, specific findings related to the construction and industry best practices for the concrete foundation were noted. The inspection scope was limited to visible foundation observations without moving or removing obstructing items.

Observations, Conclusions & Recommendations

For this inspection, it is noted that the foundation is constructed of structural brick and mortar on granite and stone footings, which are in fair to poor condition. The foundation walls are made of structural brick and mortar with gaps in the mortar joints, deteriorated bricks, water intrusion, and sagging walls due to settled footings, which require repair. Portions of the crawlspace/basement have been excavated, undermining the foundation. These areas have been coated with concrete to support the original dirt. Ideally, these areas should have had a masonry block and mortar foundation wall placed at the bottom of the slope on a concrete footing with proper reinforcement and backfilled to provide adequate support for the foundation.

Additionally, there are brick-and-mortar columns without footings in fair condition, functioning as intended. Over time, additional supports such as steel and wood posts have deteriorated at the bottom, no longer providing adequate support. The steel posts have deteriorated bottoms and are no longer adequately connected at the bottom due to excessive rust and deterioration. It is recommended that these supports be replaced with brick-and-mortar columns or 6x6 pressure-treated posts on concrete footings with appropriate connectors as required by the code.

The following are my observations, conclusions, and recommendations. The observations below were limited to what could be readily observed and did not involve any intrusive tests.

Observation #1: Damaged floor joists and beams and uneven floor in different floor locations; see Exhibit 1. **Conclusion:** The floor joists/beams and subfloor have been severely damaged for an extended period due to a leak or moisture condition. Any moisture problems contributed to decay and weakened the floor joists and subfloor. Also, there are noticeable deflections on the surface. This condition is called "creep" and is observed in buildings 40 years or older. This type of age deflection occurs when, after many years of continuous loading, the cells in the



wood change shape, and some of the fibers start to bend. Breakage and collapse seldom occur because the breaking strength of wood usually doubles its fiber bending strength. Accordingly, creeping floors tend to deflect and then set. Also, many Improper supplemental supports and beam/joists have been noticed.

Recommendation: We recommend replacing all the rotted beams/joists and adding more support in the form of new structural beams and columns, such as new wood/steel posts.

Assuming the joists are in good condition, reinforcing the floor can solve uneven floor problems. Beefing up the floor joists can diminish uneven floor issues. It is essential to demolish all the wooden structural elements of the house and build a new floor system and foundation.

Observation #2: There has been inappropriate excavation within the interior walls and middle support footings; see Exhibit 2.

Conclusion: When excavating to convert the low crawl space to a deeper level, the soil within the perimeter is excavated to the desired depth, usually done by hand. Once the footings have been exposed without adequate support or soil stabilization, the structural integrity of the home foundation will be compromised.

Recommendation: It is recommended to support the crawl space wall and middle piers foundation. This can be achieved by adding new supports such as steel posts and footings and stabilizing the soil with concrete flowable fill. Alternatively, creating a "bench ledge" by constructing a small retaining wall inside the perimeter of the foundation can help strengthen the structure and serve as a retaining wall for the soil outside the new foundation.

Observation #3: The steel posts supporting the main beams display rust damage at the base; Exhibit 3. **Conclusion:** Steel posts exposed to high humidity and moisture will eventually rust at various points. When these parts are subjected to flooding or repetitive wet conditions, they become corroded and lose their strength. **Recommendation:** If the corrosion on the steel posts or base is not severe, they should be sanded down and coated with a zinc-rich primer. Subsequently, the steel should be covered with at least two coats of acrylic paint. If the rust damage is severe, it is best to replace the affected parts entirely. This can be accomplished by cutting out the severely rusted section, attaching an elevated base, or welding a new steel post to the bottom.

Important Note: Based on our visual inspection and examination of the structural components of the foundation throughout the house, we have found that the structural elements need to be improved to meet acceptable engineering and construction standards as outlined in the 2018 IRC with 2020 Georgia Amendments. Much of the foundation needs structural support. Due to the extent of the damage and repairs required, we recommend that the house should be demolished and rebuilt as new construction from the ground up.

The conditions above render the building structurally unsafe, requiring immediate remediation and action.



Special Notice

Opinions and comments in this report are based on observations made during the inspection. Performance standards are based on the knowledge gained through the inspector's experience and professional studies. There is no warranty or guarantee, expressed or implied, regarding habitability, future performance, life, or merchantability, and no need to repair any inspected item.

Exhibits



Exhibit 1:





Exhibit 3:



REPORT PREPARED BY: Harry Wahba, P.E. Registered Professional Engineer (Lic. PE039356)





September 18, 2024

1458 Grist Mill Drive Acworth, GA. 30101 Office: (770) 318-5858 Fax: (770) 529-5279 Email: dawnmccaughtry@gmail.com

TO: Mike Wall Email: mikewall4@gmail.com

An asbestos inspection and assessment were conducted on the structure located at, 1035 Oxford Road NE, Atlanta, GA. 30306.

Mr. Robert McCaughtry completed the inspection. Mr. McCaughtry has completed the asbestos and assessment course work and passed an exam that meets all requirements for EPA/AHERA/ASHARA approved accreditation and NESHAP Regulation training. A copy of Mr. McCaughtry' Asbestos Inspectors training certificate is attached.

The asbestos survey identified air cell as suspected asbestos containing material (ACM). 10 samples of suspect materials were collected.

Samples of the suspect materials were submitted to Call Analytical Laboratories, Inc. 554 County Rd 62, Gaylesville, AL. 35973. Each sample was analyzed using Polarized Light Microscopy.

Sample ID Sample Description

- Sample #1 Kitchen, floor tile, tested negative.
- Sample #2 Utility room, linoleum, tested negative.
- Sample #3 Utility room, J.C., tested negative.
- Sample #4 Stairwell, J.C., tested negative.
- Sample #5 Left front upstairs bedroom, J.C., tested negative.
- Sample #6 Rear center bedroom, J.C., tested negative.
- Sample #7 Upstairs hallway, J.C., tested negative.
- Sample #8 Basement, boiler insulation, tested positive.
- Sample #9 Basement, air cell, tested positive.
- Sample #10 Downstairs far right room, floor tile, tested negative.

This structure has asbestos containing materials and will require abatement prior to demolition.

Mr. Robert McCaughtry



Inspection Wizards LLC

1785 Carlington Court Grayson, Georgia 30017 (678) 770-4079 www.inspectionwizards.com

Kris Bonds 1035 Oxford Road NE Atlanta, Georgia 30306

August 29, 2024

Re: Structural Foundation Evaluation

On August 29, 2024, at approximately 10:00 AM we inspected the structural foundation of the above referenced house under the direct supervision of William Hamilton, PE, CMI, for the purpose of determining whether the existing foundation is capable for supporting the existing building or an addition with improvements. The house was originally built in 1920 based on the official records. The foundation is structural brick and mortar on granite and stone footings in fair to poor condition. The footings are approximately 20x14 running continuously around the perimeter of the house, as revealed by probing in the area of the footings. The probe and handheld penetrometer also revealed an available soil bearing pressure in the range of 20500 psf. The foundation walls are structural brick and mortar with gaps in the mortar joints, deteriorated bricks, water intrusion, sagging walls where the footings have settled in need of repair. There are areas of the crawlspace / basement which have been excavated causing the foundation to be undermined. Note these areas have been coated with concrete to facilitate the support the original dirt provided. These areas should have had a masonry block and mortar foundation wall placed at the bottom of the slope on concrete footing with proper re-enforcement and backfilled to provide proper and adequate support for the foundation. In addition, to the foundation walls there are brick and mortar columns (original to the house) with no footings in fair condition, working as intended. Over time to facilitate the over spanning of the floor joist additional supports such as steel and wood posts both have deteriorated bottoms (rusted through or water damaged) so they no longer support as proposed. The steel posts are no longer joined at the bottom from the excessive rest and deterioration. Recommend these supports be replaced with brick-and-mortar columns or 6x6 pressure treated posts on concrete footings with footing to post and post to beam connectors as required by code.

The floor is a combination of beams and joists supported by the foundation walls and support columns. Many of the joists are over spanned and sagging, with and without support posts not properly designed to properly support the floor joists (single posts on individual floor joists instead of a beam to support multiple joists. There is significant water and termite damage as well as evidence of a possible fire. As can be seen on numerous joist with charring of the wood and fire sealant applied to the joists and beams. The sagging of the floor joists is observed in the house with uneven floors, cracking in the wall surfaces at the door frames, and the stairs sloping from one side to the other.

Based on the visual inspection and examination of the structural components of the foundation throughout the house (rim joists foundation walls, footers, columns, support posts and beams), we find the structural components inadequate to meet acceptable engineering and construction standards as set forth in the 2018 IRC with 2020 Georgia Amendments regarding strength, stress, loads, stability, and structural integrity. Note much of the foundation needs to be supported structurally, requiring the foundation walls to be dismantled and reconstructed on proper footing. Use of modern methods such as footing piles can not be used as the footings are brick and granite and when lifted to be supported will come apart unlike concrete footings. It is my opinion the amount of damage and repairs needed to the foundation and support foundations (columns and support posts) this house should be demolished and re-built as new construction from the ground up.

Please accept this affidavit as Building Engineer Certification that I, the undersigned, do acknowledge full proficiency with the provisions of the technical codes, other applicable laws and ordinances related to the above noted inspection. Should you have any questions or concerns please feel free to give me a call.

Respectfully submitted,

William Hamilton, CMI, PE Certified Master Inspector (309176) Professional Engineer (042917) (678) 770-4079 / BHamilton.InspWiz@gmail.com























1035 O	xford Inventory		
Assess	or: James C. Hawkins	s ISA Arborist ID: GO-002	2A/(TRAQ) Prep
Tag	Species	Location	DBH
1	Japanese Maple	Front right of property	16
2	Red Tip	Front right of home	25
3	Japanese Maple	Front right of home	10
4	Red Tip	Front left of home	15
5	Water Oak	Front left of home	50
6	Magnolia	Front left of home	12
7	Black Cherry	Front left of property	9
8	Tulip Poplar	Front left of property	19
9	Privet	Front left of property	7
10	Japanese Privet	Back right of home	20
11	Pecan	Back right of home	10
12	Silver maple	Right of shed	25
13	Red Bud	Back left of house	30
14	Japanese Maple	Back left of house	8
15	Pecan	Back middle of property	30
16	Maple	Back left of property	12
17	Tulip Poplar	Back right of property	58
18	Pine	Back right of property	30
19	Cherry Laurel	Back right of property	15
20	Mulberry	Left of shed	12
21	Mulberry	Left of shed	15
22	Pecan	Back right of property	15
23	Unknown	Back left of home	14
24	Mulberry	Back right of property	15
25	Cherry Laurel	Back right of property	8
26	Hackberry	Back right of property	8
27	Mulberry	Back right of property	11
28	Cherry Laurel	Back right of home	8
29	Mulberry	Back right of property	9

ared on 09/25/2024 on behalf of Boutte Tree
Health
Constricted root zone, healthy
Sparse canopy, Leaf spot fungal infection,decay in trunk, poor health
Healthy
Lean, leaf spot fungal infection, sparse canopy
Sparse canopy, codominant with inclusion,girdled stem, moderate deadwood in canopy, poor health
Healthy
Healthy
Lean, healthy
Invasive
Invasive
Within 5 ft of foundation/house
Lean, constricted root zone, fair health
Codominant With inclusion at base of tree, decay in inclusion, large crack running down inclusion, poor health
Within 5 ft of foundation/home
Healthy
Fungal cankers throughout trunk, poor health
Fair health
Healthy
Invasive
Undesireable species
Undesireable species
Healthy
Heavy vines, suppressed, poor structure
Undesireable species
Invasive
Healthy
Undesireable species
Invasive
Undesireable species

recommendation	DBH match	?
Retain	Yes	
Remove	Yes	
Retain	Yes	
Remove	Yes	
Remove	Yes	
Retain	Yes	
Retain	Yes	
Retain	Yes	
Remove	Yes	
Remove	Yes	
Remove	Yes	
Retain	Yes	
Remove	Yes	
Remove	Yes	
Retain	Yes	
Remove	Yes	
Retain	Yes	
Retain	Yes	
Remove	Yes	
Remove	Yes	
Remove	Yes	
Retain	Yes	
Remove	Yes	
Remove	Yes	
Remove	Yes	
Retain	Yes	
Remove	Yes	
Remove	Yes	
Remove	Yes	

































The field data upon which this plat is based has a closure precision of one foot in 15,000 feet and an angular error of 03" seconds per angle point and was adjusted using the Compass Rule. This plat has been calculated for closure and is found to be accurate within one foot in 100,000 feet.

Equipment used: Topcon GTS-213 Total Station.

FLOOD HAZARD STATEMENT

THIS PROPERTY IS NOT IN A FLOOD HAZARD AREA AS PER THE FIRM FLOOD HAZARD MAP OF DEKALB COUNTY, GEORGIA, COMMUNITY PANEL NUMBER 13089C 0062K, DATED 08/15/19

ZONING INFORMATION

CLASSIFICATION: R-85 MINIMUM LOT WIDTH - 85 FEET MINIMUM LOT AREA - 12,000 sf. SETBACKS: FRONT - 35 FEET SIDE - 8.5 FEET REAR - 40 FEET MAXIMUM LOT COVERAGE - 35% MINIMUM FLOOR AREA - 2000 sf. MAXIMUM BUILDING HEIGHT - 35 FEET

> LOT AREA: 19,110 sf. 0.438 ACRES

AS REQUIRED BY SUBSECTION (d) OF O.C.G.A. SECTION 15-6-67, THIS PLAT HAS BEEN PREPARED BY A LAND SURVEYOR AND APPROVED BY ALL APPLICABLE LOCAL JURISDICTIONS FOR RECORDING AS EVIDENCED BY APPROVAL CERTIFICATES, SIGNATURES, STAMPS, OR STATEMENTS HEREON. SUCH APPROVALS OR AFFIRMATIONS SHOULD BE CONFIRMED WITH THE APPROPRIATE GOVERNMENTAL BODIES BY ANY PURCHASER OR USER OF THIS PLAT AS TO INTENDED USE OF ANY PARCEL. FURTHERMORE, THE UNDERSIGNED LAND SURVEYOR CERTIFIES THAT THIS PLAT COMPLIES WITH THE MINIMUM TECHNICAL STANDARDS FOR PROPERTY SURVEYS IN GEORGIA AS SET FORTH IN THE RULES AND REGULATIONS OF THE GEORGIA BOARD OF REGISTRATION FOR PROFESSIONAL ENGINEERS AND LAND SURVEYORS AND AS SET FORTH IN O.C.G.A. SECTION 15-6-67.

ROBERT W. RICHARDSON, GA RLS #3419



SFI

à

¥

(60' R/W)

ROAD

OXFORD

32"OAK

19"POPLAR

ASPHALT DRIVE

54.0,

KT)) NH NH NH



The field data upon which this plat is based has a closure precision of one foot in 15,000 feet and an angular error of 03" seconds per angle point and was adjusted using the Compass Rule. This plat has been calculated for closure and is found to be accurate within one foot in 100,000 feet.

Equipment used: Topcon GTS-213 Total Station.

FLOOD HAZARD STATEMENT

THIS PROPERTY IS NOT IN A FLOOD HAZARD AREA AS PER THE FIRM FLOOD HAZARD MAP OF DEKALB COUNTY, GEORGIA, COMMUNITY PANEL NUMBER 13089C 0062K, DATED 08/15/19

ZONING INFORMATION

CLASSIFICATION: R-85 MINIMUM LOT WIDTH - 85 FEET MINIMUM LOT AREA - 12,000 sf. SETBACKS: FRONT - 35 FEET SIDE - 8.5 FEET REAR - 40 FEET MAXIMUM LOT COVERAGE - 35% MINIMUM FLOOR AREA - 2000 sf. MAXIMUM BUILDING HEIGHT - 35 FEET

LEGEND

IPF = 1/2'' REBAR FOUND
IPS = 1/2'' REBAR PIN SET
L.L. = LAND LOT
L.L.L. = LAND LOT LINE
PI = PROPERTY I INE
CL = CENTERLINE
$D.L. = DOILDING LINE D/W = DICUT_OE_WAY$
R = ROMEOFEWAN
S.S.E. = SANITART SEWER EASEMENT
D.E. = DRAINAGE EASEMENT
MH = MANHOLE
C.B. = CAICH BASIN
J.B. = JUNCTION BOX
HW = HEADWALL
D.I. = DROP INLET
PP = POWER/UTILITY POLE
F.H. = FIRE HYDRANT
I.E. = INVERT ELEVATION
F.F.E. = FINISHED FLOOR ELEVATION
F.F.B. = FINISHED FLOOR BASEMENT
F.F.G. = FINISHED FLOOR GARAGE
BOC = BACK OF CURB
FP = FDGF OF PAVEMENT
N/F = NOW OR FORMERIY
$P \cap B = POINT \cap F BEGINNING$
SS -= SANITARY SEWER LINE / PIPE
-X - X - X - = FENCE INF
= STORM SEWER LINE/FIFE
w w = water line
G = GAS LINE
CM = CONCRETE MONUMENT
C.E. = CONSTRUCTION EASEMENT
$C_{C} = C_{C} + C_{C$
$L_{3} = Lighti Standard OTD - ODEN TOD DIDE FOUND$

 And Runch Cle Leox
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shifting
 For Shifting

 New of Weighting
 For Shifting
 For Shifting
 For Shif

PROPOSED LOT COVERAGE:

ì

\$

ROAD (60. R/W)

OXFORD

100.00

54.0,

HOUSE = 2512 sf.DRIVEWAY = 2034 sf.FRONT WALK = 136 sf.FRONT PORCH = 50 sf.REAR PORCH = 824 sf.

TOTAL = 5556 sf. LOT COVERAGE = 29.07%







NOT FOR CONSTRUCTION
Drawn: Checked: Date: Job No.: Revisions: No. Date
1035 OXFORD ROAD A NEW CUSTOM HOUSE PROJECT ATLANTA, GEORGIA
THIS DRAWING IS AN INSTRUMENT OF SERVICE AND SHALL REMAIN THE REPORTORY OF THE AND SHALL REMAIN THE THOSE OF THE SHALL BE REPRODUCED OR TRANSMITED IN ANY FORM OR BY ANY MENS, ELECTRONIC OR MECHANICAL, FOR ANY DURPOSE, WITHOUT THE EXPRESS WRITTEN PERMISSION OF THE ARCHITECT.
GOODMAN DESIGN P.O. BOX 1296 ALPHARETTA, GEORGIA 30009 ph. (678) 427-8466 e. brant@goodmandesign.us www.goodmandesign.us creating architecture for sustainable environments create. Process. Design with Purpose.
Title: EXTERIOR ELEVATIONS Scale: 1/4"=1'-0"
Sheet: A201 of:



	NOT FOR CONSTRUCTION
Draw Chec Date Job	'n: :ked: : No.:
Revis No.	sions: Date
	1035 OXFORD KOAD A NEW CUSTOM HOUSE PROJECT ATLANTA, GEORGIA
This df and sh Ard sh Be rep or by For an Written	AWING IS AN INSTRUMENT OF SERVICE ALL RELAWN THE PROPERTY OF THE RODUCED OR TRANSMITTED IN ANY FORM ANY MEANS, ELECTRONIC OR MECHANICAL, Y PURPOSE, WITHOUT THE EXPRESS PERMISSION OF THE ARCHITECT.
GOODMAN DESIGN	P.O. BOA 1290 ALPHARETTA, GEORGIA 30009 ph. (678) 427-8466 e. brant@goodmandesign.us www.goodmandesign.us creating architecture for sustainable environment: create. Process. Design with Purpose
Title: E EL Scale 1	EXTERIOR EVATIONS ~ /4"=1'-0"
Shee of:	A 202





NOT FOR CONSTRUCTION
Drawn: Checked: Date: Job No.: Revisions: No. Date
1035 OXFORD ROAD A NEW CUSTOM HOUSE PROJECT ATLANTA, GEORGIA
THIS DRAWING IS AN INSTRUMENT OF SERVICE AND SHALL REMAIN THE PROPERTY OF THE ARCHTECT. NO PART OF THIS DOUMENT SHALL BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS ELECTRONIC OR MECHANICAL.
GOODMAN DESIGN P.O. BOX 1296 ALPHARETTA, GEORGIA 30009 ph. (678) 427-8466 e. brant@goodmandesign.us www.goodmandesign.us creating architecture for sustainable environments Create. Process. Design with Purpose.
Title: EXTERIOR ELEVATIONS Scale: 1/4"=1'-0" Sheet:
A203



	NOT FOR CONSTRUCTION
	Drawn: Checked: Date: Job No.: Revisions: No. Date
	1035 OXFORD ROAD A NEW CUSTOM HOUSE PROJECT ATLANTA, GEORGIA
╟	THIS DRAWING IS AN INSTRUMENT OF SERVICE AND SHALL REMAIN THE PROPERTY OF THE ACHITECT. NO PART OF THIS DOCUMENT BE BY ANY MEANS, ELECTRONIC OR MECHANICAL, FOR ANY PURSE, WITHOUT THE EXPRESS WRITTEN PERMISSION OF THE ARCHITECT.
	GOODMAN DESIGN P.O. BOX 1296 ALPHARETTA, GEORGIA 30009 ph. (678) 427-8466 e. brant@goodmandesign.us www.goodmandesign.us creating architecture for sustainable environments create. Process. Design with Purpose
	Title: EXTERIOR ELEVATIONS Scale: 1/4"=1'-0"
	Sheet: A204 of:

NOT FOR CONSTRUCTION
Drawn: Checked: Date: Job No.: Revisions: No. Date
1035 OXFORD ROAD A NEW CUSTOM HOUSE PROJECT ATLANTA, GEORGIA
\l

Title:

Sheet:

EXTERIOR ELEVATIONS

Scale: 1/4"=1'-0"

A202

N		
9'-1" PLATE HEIGHT	BRICK VENEER, TYP. ASPHALT SHINGLE ROOFING, TYP.	
10'-1" PLATE HEIGHT	▼	
	BRICK VENEER, TYP	

ASPHALT SHINGLE – ROOFING, TYP.

NOT FOR CONSTRUCTION Drawn: Drawn: Checked: Date: Job No.: Revisions: No. Date Image: Image:
PROJECT
1035 OXFORD F A NEW CUSTOM HOUSE F ATLANTA, GEORGIA
SIGN BIA 30009 BIA 30009 GIA 30009 GIA 300005 s grant mean the backets and start of twister the service of the service of the service softwirten between the service of the service with Purpose.
Create. Process.

-##4 ==

NOT FOR CONSTRUCTION
Drawn: Checked: Date: Job No.: Revisions: No. Date
1035 OXFORD ROAD A NEW CUSTOM HOUSE PROJECT ATLANTA, GEORGIA
THIS DRAWING IS AN INSTRUMENT OF SERVICE AND SHALL REMAIN THE PROPERTY OF THE ARCHITECT. NO PART OF THIS DOCUMENT SHALL BE REPRODUCED OR TRANSMITED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, FOR ANY PURPOSE, WITHOUT THE EXPRESS WRITTEN PERMISSION OF THE ARCHITECT.
GOODMAN DESIGN P.O. BOX 1296 ALPHARETTA, GEORGIA 30009 ph. (678) 427-8466 e. brant@goodmandesign.us www.goodmandesign.us creating architecture for sustainable environments create. Process. Design with Purpose.
Title: EXTERIOR ELEVATIONS Scale: 1/4"=1'-0" Sheet: A204
of:

NOT FOR CONSTRUCTION
Drawn: Checked: Date: Job No.: Revisions:
No. Date
1035 OXFORD ROAD A NEW CUSTOM HOUSE PROJECT ATLANTA, GEORGIA
THIS DRAWING IS AN INSTRUMENT OF SERVICE AND SHALL REMAIN THE PROPERTY OF THE ARCHITECT. NO PART OF THIS DOCUMENT SHALL BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, FOR ANY PURPOSE, WITHOUT THE EXPRESS WRITTEN PERMISSION OF THE ARCHITECT.
GOODMAN DESIGN P.O. BOX 1296 ALPHARETTA, GEORGIA 30009 ph. (678) 427-8466 e. brant@goodmandesign.us www.goodmandesign.us creating architecture for sustainable environments create. Process. Design with Purpose.
Title: EXTERIOR ELEVATIONS Scale: 1/4"=1'-0" Sheet:
A201

NOT FOR CONSTRUCTION
Drawn: Checked: Date: Job No.: Revisions: No. Date
1035 OXFORD ROAD A NEW CUSTOM HOUSE PROJECT ATLANTA, GEORGIA
THIS DRAWING IS AN INSTRUMENT OF SERVICE AND SHALL REMAIN THE PROPERTY OF THE ARCHITECT. NO PART OF THIS DOCUMENT SHALL BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, FOR ANY PERPOSE, WITCH THE LARCHITECT.
GOODMAN DESIGN P.O. BOX 1296 ALPHARETTA, GEORGIA 30009 ph. (678) 427-8466 e. brant@goodmandesign.us www.goodmandesign.us creating architecture for sustainable environments create. Process. Design with Purpose
Title: EXTERIOR ELEVATIONS Scale: 1/4"=1'-0" Sheet:
A201

NOT FOR CONSTRUCTION
Drawn: Checked: Date: Job No.: Revisions: No. Date
1035 OXFORD ROAD A NEW CUSTOM HOUSE PROJECT ATLANTA, GEORGIA
<section-header><section-header><section-header><text><text><text><text><text></text></text></text></text></text></section-header></section-header></section-header>

