

Development Services Center 178 Sams Street Decatur, GA 30030 www.dekalbcountyga.gov/planning 404-371-2155 (o); 404-371-4556 (f)

Chief Executive Officer
Michael Thurmond

DEPARTMENT OF PLANNING & SUSTAINABILITY

Interim Director Cedric Hudson

Application for Certificate of Appropriateness

Date submitted: 8 - 22 - 202	+	Date Rece	eived:			
Address of Subject Property: 138	4 Harvar	d Rd.				
Applicant: Amanda Jo	hnson		E-Mail:	Aman	da C Small carpe	ntevs.con
Applicant: Amanda Jo Applicant Mailing Address: Sma	all Carper	HUB.			Dekalb Ave, A 30307	
Applicant Phone: 404 . 688	1.7665		-			
Applicant's relationship to the owner	: Owner	Archit	cect Contract	tor/Builder	Other	
**************************************			,			
Owner(s):			Email:			
Owner(s) Mailing Address: 1384	1 Harvar	1 Ro	1., Atlanta	GA.	30306	
Owner(s) Telephone Number: 4:1	4 210-	550	5			
					_	2.0
Approximate date of construction of t	he primary structu	ure on the p	property and any other	structures a	ffected by this project: 197	<u> </u>
Nature of work (check all that apply):	New construction		New Accessory Building		Other Building Changes	X i
	Demolition		Landscaping		Other Environmental Changes	
	Addition		Fence/Wall		Other	
Description of Work:	Moving a Building		Sign Installation			
The Unisting windows of replace all of the sashes condensation has cause of the sashes with him divided was with 518" but of the original windows, a who damaged by ond be This form must be completed in its photographs, etc. All documents she application and supporting material application will not be accepted.	entirety and be acould be in PDF for to plansustain@	companied ormat, exce dekalbcour	Apender bills v d by supporting docume opt for photographs, we htyga.gov and pvjennin	VC WE pents, such as which may bugs@dekalbc	plans, list of materials, color e in JPEG format. Email the ountyga.gov. An incomplete	samples,
including a 4-life glass previous boards	Signature of A	pplicant:	Menda	May		



DEPARTMENT OF PLANNING & SUSTAINABILITY

Authorization of a Second Party to Apply for a Certificate of Appropriateness

This form is required if the individual making the request is **not** the owner of the property.

I/We: Ann Lynn
being owner(s) of the property at: 1384 Harvard Rd., Atlanta, GA 30306
hereby delegate authority to: Amanda Johnson
to file an application for a certificate of appropriateness in my/our behalf.
Signature of Owner(s):
Signature of Owner(s):
Date: 8.22.2024

Please review the following information

Approval of this Certificate of Appropriateness does not release the recipient from compliance with all other pertinent county, state, and federal regulations.

Before making any changes to your approved plans, contact the preservation planner (404/371- 2155). Some changes may fall within the scope of the existing approval, but others will require review by the preservation commission. If work is performed which is not in accordance with your certificate, a Stop Work Order may be issued.

If your project requires that the county issue a Certificate of Occupancy at the end of construction, an inspection may be made to verify that the work has been completed in accord with the Certificate of Appropriateness. If the work as completed is not the same as that approved in the Certificate of Appropriateness you will not receive a Certificate of Occupancy. You may also be subject to other penalties including fines and/or required demolition of the non-conforming work.

If you do not commence construction within twelve months of the date of approval, your Certificate of Appropriateness will become void and you will need to apply for a new certificate if you still intend to do the work.

1384 Harvard Rd.



Figure 1: Front elevation as seen from street



Figure 2: Back elevation




Figure 3: Driveway side elevation



Figure 4: Right side elevation




Figure 5: Front triple window unit



Figure 6: Front dormer window



Figure 7: Front door



Figure 8: Front door carpenter bee damage



Figure 9: Cracked windowpane at front dormer



Figure 10: Window sash rot from condensation water damage



 $Figure\ 11:\ Window\ sash\ rot\ from\ condensation\ water\ damage$



 $Figure~{\it 12: Window~sash~rot~from~condensation~water~damage}$